

SRWTP Odor events

2004-2005 SRWTP Odor Events	
Date	Description
March 2004	Odors were reported by Plant staff near the intersection of Laguna Blvd and I-5. The odors may have been generated from the plants solid storage basins. Fans around the basins are used to mitigate odors, however only some of the fans were on at the time.
September 2004	Resident reported very strong odors near the south side of plant boundary at Laguna Blvd. The odors may have been generated from the plants solid storage basins.
September 2004	Odors were reported by two different plant employees near the intersection of I-5 and Laguna Blvd. The cause of the odors was likely from partially treated sewage (Primary Effluent) being stored in the plants on-site storage basins for an extended period of time. The sewage was drained from the storage basins to eliminate the odors.
March 2005	Strong odors were reported by a resident along the south side of the plant boundary. The odors were likely generated from the solid storage basins. The basins fans were turned on to mitigate the odor.

2006

There were no SRWTP odor events in 2006

2007

There were no SRWTP odor events in 2007